



Development of Engineered Ceramic Matrix Composites

S. V. Raj¹ (PI), R. Bhatt² and M. Singh²

1) Glenn Research Center, Cleveland, OH

2) Ohio Aerospace Institute, Cleveland, OH

Acknowledgements

Technicians: Mr. Ray Babuder; Mr. Robert Angus; Mr. Ronald Phillips & Mr. Daniel Gorican

Program Manager: Dr. Koushik Datta

Funding: NASA's ARMD Seedling Fund Phases I & II



Introduction

- **Advanced aircraft engines require the use of reliable, lightweight, creep-resistant and environmentally durable materials.**
- **Silicon carbide-based ceramic matrix composite (CMC) technology is being developed to replace nickel-based superalloy blades and vanes.**
 - **Near term 1589 K (2400 °F) (cooled).**
 - **Medium term 1755 K (2700 °F) (cooled).**




Factors Affecting Composite Properties

NASA Aeronautics Research Institute

Composites are engineered systems, whose properties depend on:

- Fiber properties
- **Matrix properties**
- Interfacial properties
- Volume fractions of the constituents
- Processing
- Fiber weave architecture
- Fiber coatings
- Protective coatings (e.g. EBCs, TBCs)







Typical Microstructures of As-Processed BN-Coated Hi-Nicalon MI SiC Composites

NASA Aeronautics Research Institute

(Courtesy M. Singh)




Density ~ 96-97 %



Current SiC/SiC CMC Matrix Capabilities

NASA Aeronautics Research Institute



- Matrix fills space and provides a thermally conductive path.
- Fracture toughness due to crack bridging and interface debonding.
- Relatively low matrix cracking strength - $\sigma_{\text{design}} < \sigma_{\text{proportional limit}}$

- Brittle at all temperatures.
- No crack tip blunting – fast crack propagation.
- No self-healing.
- Oxygen ingress to fibers shortens fiber life.
- Free Si in the matrix limits temperature usage (melting point of Si: 1687 K; 1414 °C; 2577 °F).





Recession of BN and Formation of Glassy Phase in BN-Coated Hi-Nicalon MI SiC Composites

NASA Aeronautics Research Institute

(Courtesy M. Singh)

T = 973 K; σ = 250 MPa; 1000 h in air



B_2O_3 - SiO_2 : Low eutectic temperature of 372°C



Important Question


NASA Aeronautics Research Institute

**Can the matrix constituents be suitably engineered to develop
a new generation of Engineered Matrix (Ceramic) Composites
(EMCs) with improved properties and tailored for a specific
component?**



Crack Tip Blunting and Self-Healing

NASA Aeronautics Research Institute





Innovation and Expected Impact

NASA Aeronautics Research Institute

- ❖ **High temperature matrix** - greater than 1589 K (1315 °C/2400 °F)
- ❖ **Matrix plasticity** - increased reliability, compliant matrix.
- ❖ **Chemical and thermal strain compatibility** with the coated SiC fibers.
- ❖ **Self-healing matrix** - prevents or minimizes oxygen ingress.
- ❖ **Low free Si** - reduces fiber attack, reduces incipient melting, increased high temperature capability.
- ❖ **Dense matrix** - high thermal conductivity.



Historical Perspective

Pre-1980s

Current

Concept



Monolithic
ceramics

Ceramic matrix
composites (CMCs)

Engineered matrix
composites (EMCs)

Low toughness
Low strength

Higher toughness
Higher strength
Free silicon

Crack blunting &
self-healing
Low free silicon
Higher toughness
Higher strength
Higher temperature



Technical Approach

NASA Aeronautics Research Institute

- **Plasticity** – Introduce a chemically stable metallic silicide.
- **Temperature capability** – Choose silicides with melting points higher than that of Si (m.p. 1687 K; 1414 °C; 2577 °F).
- **Thermal expansion** – Match thermal expansion of the engineered matrix (EM) with the SiC fibers.
- **Self-healing capability** – Add constituents to heal cracks with low viscosity oxides or silicates.
- **Low Si** – Melt infiltrate with silicide instead of Si.
- **Dense EMCs** – Slurry infiltration and melt infiltration.




Silicide Additives

- CrSi_2
- MoSi_2
- TiSi_2
- WSi_2
- CrMoSi alloy



Matching Thermal Strains: Theoretical Concept

NASA Aeronautics Research Institute





Matrix Design Concept

NASA Aeronautics Research Institute

$$(\Delta L/L_0)_{\text{fiber}} = (\Delta L/L_0)_{\text{EM}} = V_{\text{silicide}}(\Delta L/L_0)_{\text{silicide}} + V_{\text{SiC}}(\Delta L/L_0)_{\text{SiC}} + V_{\text{Si}_3\text{N}_4}(\Delta L/L_0)_{\text{Si}_3\text{N}_4}$$

<u>Concept</u>	<u>$V_{\text{silicide}} (\%)$</u>	<u>$V_{\text{SiC}} (\%)$</u>	<u>$V_{\text{Si}_3\text{N}_4} (\%)$</u>
Traditional	0	100	0
Present investigation	x	(100-x-y)	y




Objectives

- Evaluate different engineered matrices based on theoretical concepts.
- **Proof of concept: Demonstrate thermal strain compatibility with SiC.**
- Evaluate bend and oxidation properties.
- Evaluate self-healing compositions.
- Fabricate and test engineered matrix composites.



Matrix Processing Steps

NASA Aeronautics Research Institute





NASA Aeronautics Research Institute


Hot-Pressed Plate and Optical Micrograph

CrMoSi/SiC/Si₃N₄ (CrMoSi-EM)

50 x 50 x 4 mm




Optical micrograph





Back Scattered Image and Energy Dispersion Spectra: CrMoSi/SiC/Si₃N₄ (CrMoSi-EM)


NASA Aeronautics Research Institute





Proof-of-Concept: Thermal Strains


NASA Aeronautics Research Institute





Macrograph of the Surface of a Thermally Cycled CTE MoSi₂/SiC/Si₃N₄ Specimen

NASA Aeronautics Research Institute




- MoSi₂/SiC/Si₃N₄ engineered matrix dropped from the program.



Isothermal Oxidation Behavior of Engineered Matrices

NASA Aeronautics Research Institute




$\text{TiSi}_2/\text{SiC}/\text{Si}_3\text{N}_4$ and $\text{WSi}_2/\text{SiC}/\text{Si}_3\text{N}_4$ engineered matrices dropped from the program



Four-Point Bend Stress-Strain Curves for a CrSi_2 Engineered Matrix

NASA Aeronautics Research Institute




- Crack blunting due to crack tip plasticity increases bend strength



Four-Point Bend Stress-Strain Curves for a CrMoSi Engineered Matrix


NASA Aeronautics Research Institute





CT Scan and a Schematic of the BN-Coated SiC/SiC Preform

NASA Aeronautics Research Institute



CT Scan




Schematic of void distribution

Void volume fraction $\sim 25\%$



Steps in Engineered Matrix Composite Fabrication


NASA Aeronautics Research Institute





Epoxy pressure infiltration unit


NASA Aeronautics Research Institute





Microstructures of TiSi_2 -EM-Infiltrated SiC Fiber Preform

NASA Aeronautics Research Institute






CT Scans of $\text{TiSi}_2/\text{SiC}/\text{Si}_3\text{N}_4$


Particulate Epoxy and Si- Melt Infiltrated Preform

NASA Aeronautics Research Institute


As-received
Preform




Particulate
Infiltrated



Pyrolyzed



Si Melt
Infiltrated



Area fraction of
porosity ~ 21-23%

Area fraction of
porosity ~ 0.9%

Area fraction of
porosity ~ 6.6%


Area fraction of
porosity ~ 1.8%

The red
regions are
voids



TiSi₂/SiC/Si₃N₄ epoxy infiltrated preforms





NASA Aeronautics Research Institute





CrMoSi/SiC/Si₃N₄ Epoxy Infiltrated Preforms


NASA Aeronautics Research Institute






Particulate and Silicon Melt Infiltrated SiC/SiC Preforms


NASA Aeronautics Research Institute





Room Temperature Bend Stress-Strain Curves for CrMoSi EMCs


NASA Aeronautics Research Institute






Preliminary Studies: Bend Strengths of CrMoSi-SiC-Si₃N₄-Si EMCs

NASA Aeronautics Research Institute



Heat treated in air at 1600 K for 50 h








Preliminary Studies:

Bend Strengths of CrMoSi-SiC-Si₃N₄-SiGe EMCs

NASA Aeronautics Research Institute



Heat treated in air at 1600 K for 50 h






Assessment of the Self-Healing Characteristics of Different Additives to CrMoSi-SiC at 1600 K


NASA Aeronautics Research Institute

Pre-drilled hole
~ 1 mm dia.


Before Oxidation



After Oxidation for 24 h




- CrB₂ addition shows the best ability to heal scratches




Self-Healing of CrMoSi-SiC with 5%CrB₂ at 1700 K after 100 h

NASA Aeronautics Research Institute


Top Face




Rear Face




1700 K/100 h




1700 K/100 h





Self-Healing Characteristics of CrMoSi-SiC-CrB₂ Oxidized at 1700 K for 100 h

NASA Aeronautics Research Institute






Self-Healing Studies (in progress)

NASA Aeronautics Research Institute

Cracks emanating from a Vickers indent




Perform qualitative healing studies on indented matrices to demonstrate crack healing.




Dynamic Loading Studies (in progress)

NASA Aeronautics Research Institute



Notched specimens will be tested in air and inert gas to demonstrate that the air-tested specimens are stronger than those tested in inert gas due to self-healing of cracks.




Optical Micrographs of Single Edge Pre-Cracked Beam (SEPB) Specimens Studies

NASA Aeronautics Research Institute


Unoxidized




Unoxidized



Oxidized
Top
Surface




Oxidized
Bottom
Surface





Cr-Si Binary Phase Diagram



NASA Aeronautics Research Institute





CrSi₂-Melt Infiltrated Tyranno SA Preforms


NASA Aeronautics Research Institute





Composition Analysis of the CrSi₂-SiC Fiber Interface

NASA Aeronautics Research Institute



No reaction of CrSi₂ with SiC – consistent with thermodynamic calculations



Summary and Conclusions

NASA Aeronautics Research Institute

- **A concept for developing a new class of high temperature engineered matrix composites (EMCs) with crack blunting, self-healing and low Si capabilities using intermetallic silicides is proposed.**
- **The following concepts have been demonstrated:**
 - Thermal expansion of the engineered matrix can be matched with that of SiC.
 - Increased matrix ductility can lead to higher bend strengths due crack blunting.
 - Promising self-healing additives have been identified.
 - CrSi₂/SiC/Si₃N₄ and CrMoSi/SiC/Si₃N₄ engineered matrices have been identified for 1589 K (2400 °F) and 1755 K (2700 °F).
- **Several new compositions have been formulated for further studies.**
- **Fabrication of dense EMCs has proved to be challenging due to insufficient particle infiltration in the coated SiC/SiC woven preforms and due to poor capillarity action of the Cr-Si alloys.**



Distribution and Dissemination

NASA Aeronautics Research Institute

- **Applied for US Patent (May 30, 2013) –NASA Docket No: LEW 18964-1**

Title: Engineered Matrix Self-Healing Composites

S/N: 13/905,333; Filed: 5/30/13

Inventors: Sai Raj, Mrityunjay Singh, Ramakrishna Bhatt

- **S. V. Raj, M. Singh and R. Bhatt, “High-Temperature, Lightweight, Self-Healing Ceramic Composites for Aircraft Engine Applications”, NASA Tech Briefs, vol. 37, No. 2, p. 40 February 2013;
<http://www.techbriefs.com/component/content/article/5-ntb/tech-briefs/materials/15663-lew-18964-1>.**
- **S. V. Raj, M. Singh and R. Bhatt, “Preliminary Studies on the Development of Engineered Matrices for SiC Fiber-Reinforced Ceramic Composites”, 38th Annual Conference on Composites, Materials and Structures, Cocoa Beach, FL Jan 26-30, 2014**
- **Journal paper submitted for DAA 1676 management approval.**



Next Steps

- The research has been transferred to ARMD's Aero Sciences Program (FY 14).
- Methods to increase particulate loading and silicide melt infiltration of the preforms are being studied.
- Dynamic fracture toughness tests are underway to quantify the self-healing capabilities of several engineered matrices.
- Bend and tensile creep tests of several engineered matrix specimens are planned.